

# A & A Collision Centers

919 E. Orange Grove Blvd., Pasadena , CA 91104  
 (626) 794-7750  
 Fax: (626) 794-7749  
 Email: aacollisioncenters@yahoo.com

Damage Assessed By: VICTOR OGANESYAN

Deductible: UNKNOWN

Mitchell Service: 910969

Description: 2007 Porsche 911 Turbo  
 Body Style: 2D Cpe  
 OEM/ALT: O

Drive Train: 3.6L Turbo Inj 6 Cyl 6M AWD  
 Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	AUTO	BDY	OVERHAUL	Frnt Bumper Cover Assy			3.7
2	000008	BDY	REMOVE/REPLACE	Frnt Bumper Cover	997 505 191 04	1,114.22	INC
3	AUTO	REF	REFINISH	Frnt Bumper Cover			C 2.7
4	000013	BDY	REMOVE/REPLACE	L Frt Otr Bumper Grille	997 505 563 01 01C	187.86	INC
5	000014	BDY	REMOVE/REPLACE	Frnt Ctr Bumper Grille	997 505 541 02 01C	91.67	INC
6	000015	BDY	REMOVE/REPLACE	Frnt Lwr Bumper Spoiler	997 505 557 01 01C	235.15	INC
7	000020	BDY	REMOVE/REPLACE	L Frt Otr Bumper Retaining Strip	997 505 535 01	21.84	INC #
8	000023	BDY	REMOVE/REPLACE	Frnt Ctr Bumper Retaining Strip	997 505 531 00	54.37	INC #
9	000024	BDY	REMOVE/REPLACE	Frnt Bumper Insert	997 505 777 00	57.09	INC
10	000034	BDY	REMOVE/REPLACE	Frnt Bumper Reinforcement	997 505 141 02	178.93	INC #
11	000028	BDY	REMOVE/REPLACE	L Frnt Bumper Impact Absorber	997 505 319 00	123.10	0.4 #
12	001637	BDY	REMOVE/INSTALL	R Headlamp Assy			INC
13	000058	BDY	REMOVE/REPLACE	L H/Lamp Assembly	997 631 157 23	1,298.94	0.2
14	AUTO	BDY	CHECK/ADJUST	Headlamps			0.4
15	000075	BDY	REMOVE/REPLACE	L Frnt Signal Lamp Assembly	997 631 091 03	474.32	INC #
16	000096	BDY	REPAIR	Hood Panel	Existing		5.0*
17	AUTO	REF	REFINISH	Hood Outside			C 2.4
18	000106	BDY	REMOVE/REPLACE	Hood Latch	997 511 053 00	79.79	0.6 #
19	000110	BDY	REMOVE/REPLACE	Hood Latch Release	997 624 119 00	57.18	
20	000113	BDY	REMOVE/REPLACE	Frnt Hood Trim	997 504 811 04 FMT	27.95	INC
21	001661	BDY	REMOVE/INSTALL	R Fender Assy			2.8 #
22	000123	BDY	REMOVE/REPLACE	L Fender Panel	997 503 031 00 GRV	424.37	3.2 #
23	AUTO	REF	REFINISH	L Fender Outside			C 1.6
24	AUTO	REF	REFINISH	L Add To Edge Fender			C 0.5
25	000137	BDY	REMOVE/INSTALL	R Fender Front Liner	Existing		INC #r
26	000138	BDY	REMOVE/REPLACE	L Fender Front Liner	997 504 123 01	148.82	INC #
27	000139	BDY	REMOVE/INSTALL	R Fender Rear Liner	Existing		INC #r
28	000140	BDY	REMOVE/REPLACE	L Fender Rear Liner	997 504 203 01	136.09	INC #
29	000148	BDY	REMOVE/REPLACE	L Fender Nut 6@0.20	999 049 007 40	1.20	
30	000191	BDY	REMOVE/INSTALL	Front Body Trunk Lining	Existing		0.3 r
31	000198	BDY	REMOVE/INSTALL	Front Body Trunk Lining	Existing		0.4 r
32	000200	BDY	REMOVE/INSTALL	Lining	Existing		0.5 r
33	001877	MCH	REMOVE/REPLACE	L Frnt Susp Wheel Hub	997 341 607 02	435.81	INC #
34	000310	MCH	REMOVE/REPLACE	L Frnt Susp Bearing Retainer	986 331 661 20	18.52	INC #
35	000312	MCH	REMOVE/REPLACE	L Frnt Susp Wheel Bearing	999 053 054 05	109.39	INC #
36	000314	MCH	REMOVE/REPLACE	L Frnt Susp Steering Knuckle	997 341 165 24	801.13	3.5 #

ESTIMATE RECALL NUMBER: 02/11/2011 14:31:10 875

Mitchell Data Version: OEM: JAN\_11\_V

UltraMate is a Trademark of Mitchell International  
 Copyright (C) 1994 - 2011 Mitchell International

UltraMate Version: 7.0.226

All Rights Reserved

37	000344	MCH	REMOVE/REPLACE	L Lwr Frt Susp Control Arm Assy	-M	997 341 053 04	359.33	0.7	#
38	000346	MCH	REMOVE/REPLACE	L Lwr Frt Susp Track Arm	-M	997 341 043 00	229.51	0.6	#
39	000348	MCH	REMOVE/REPLACE	L Frt Susp Plate	-M	997 341 145 05	18.52	INC	#
40	000352	MCH	REMOVE/REPLACE	L Frt Susp Strut Bar	-M	997 504 433 01	17.28	INC	#
41	000354	MCH	REMOVE/REPLACE	L Frt Susp Stab Bar Link	-M	997 343 073 03	65.37	0.4	#
42	000355	MCH	REMOVE/REPLACE	Frt Susp Stabilizer Bar	-M	997 343 703 08	193.61	1.2	#
43	000360	MCH	REMOVE/REPLACE	Frt Susp Crossmember	-M	997 341 081 11	801.13	3.7	#
44	000362	MCH	REMOVE/REPLACE	L Headlamp Aim Control Sensor	-M	997 631 121 00	79.91	0.9	#
45	000364	MCH	REMOVE/REPLACE	L Link Rod	-M	997 341 375 01	23.12	INC	#
46	000365	MCH	REMOVE/REPLACE	L Frt Drive Axle Shaft Brkt	-M	996 341 371 03	3.71	INC	#
47	000367	MCH	REMOVE/REPLACE	L Frt Drive Axle Shaft Assembly	-M	997 349 038 01	636.82	0.4	#
48	000386	MCH	REMOVE/REPLACE	L Steering Tie Rod End	-M	996 347 131 04	88.29	INC	
49	000392	MCH	REMOVE/REPLACE	L Inr Steering Tie Rod	-M	997 347 322 01	106.55	0.6	#
50	000394	MCH	REMOVE/REPLACE	L Otr Steering Protect Boot	-M	997 347 191 00	10.88	INC	#
51	000874	BDY	REPAIR	L Frt Door Shell		Existing		5.0*	#
52	AUTO	REF	REFINISH	L Frt Door Outside					C 1.8
53	001701	REF	REFINISH	L Frt Mirror Complete					C 0.8
54	001709	BDY	REMOVE/INSTALL	L Frt Otr Door Belt Weatherstrip					1.4 #
55	001711	BDY	REMOVE/INSTALL	L Frt Rear View Mirror					INC #
56	001713	BDY	REMOVE/INSTALL	L Frt Door Trim Panel					INC #
57	001721	BDY	REMOVE/INSTALL	L Frt Otr Door Handle					0.4 #
58	001731	BDY	REMOVE/INSTALL	L Roof Moulding					0.3
59	001005	BDY	REMOVE/INSTALL	L Roof Seal		Existing			1.2 r
60	001736	GLS	REMOVE/INSTALL	Back Window					0.3 #
61	001050	GLS	REMOVE/REPLACE	Back Window Adhesive		000 043 301 14	132.16		
62	001060	BDY	REMOVE/REPLACE	L Quarter Outer Panel		997 503 961 12 GRV	2,163.72	26.0	#
63	AUTO	REF	REFINISH	L Quarter Panel Outside					C 1.8
64	AUTO	REF	REFINISH	L Quarter Panel Edge					C 0.5
65	AUTO	REF	REFINISH	L Add For Pillar					C 0.5
66	001080	BDY	REMOVE/REPLACE	L Quarter Wheelhouse Panel		997 502 215 05 GRV	526.23	6.5	
67	001090	BDY	REMOVE/REPLACE	L Quarter Body Side Panel		997 502 115 00 GRV	53.66	3.0	
68	001092	BDY	REMOVE/REPLACE	L Quarter Wheelhouse Liner		997 504 573 06	131.01	INC	
69	001755	GLS	REMOVE/INSTALL	L Quarter Glass					0.3 #
70	001115	BDY	REMOVE/REPLACE	Qtr Glass Adhesive		N.A.	25.00	*	
71	001756	REF	BLEND	Engine Lid					C 0.8
72	001758	BDY	REMOVE/INSTALL	Engine Lid Assy					1.0
73	001759	REF	REFINISH	Spoiler					C 1.2
74	001143	BDY	REMOVE/INSTALL	Engine Lid Spoiler		Existing			1.0 r
75	001155	MCH	REMOVE/REPLACE	L Rear Susp Hub Assy	-M	997 331 605 00	348.83	INC	#
76	001159	MCH	REMOVE/REPLACE	L Rear Susp Wheel Bearing	-M	999 053 055 02	110.20	INC	#
77	001161	MCH	REMOVE/REPLACE	L Rear Susp Bearing Retainer	-M	996 331 661 01	18.52	INC	#
78	001181	MCH	REMOVE/REPLACE	L Rear Susp Hub Carrier	-M	997 331 111 07	534.05	3.2	#
79	001185	MCH	REMOVE/REPLACE	L Upr Rear Susp Front Link	-M	997 331 047 01	136.60	0.4	#
80	001187	MCH	REMOVE/REPLACE	L Upr Rear Susp Rear Link	-M	997 331 047 01	136.60	INC	#
81	001189	MCH	REMOVE/REPLACE	L Lwr Rear Susp Control Arm	-M	997 331 053 02	404.67	INC	#
82	001195	MCH	REMOVE/REPLACE	L Lwr Rear Susp Front Link	-M	997 331 043 01	232.11	0.4	#
83	001197	MCH	REMOVE/REPLACE	L Lwr Rear Susp Rear Link	-M	997 331 045 04	172.33	INC	#
84	001201	MCH	REMOVE/REPLACE	L Rear Susp Shock Absorber	-M	997 333 053 24	551.67	0.8	#
85	001222	MCH	REMOVE/REPLACE	L Rear Susp Stabilizer Link	-M	ORDER FROM DEALER	47.47	0.6	#
86	001500	BDY	REMOVE/REPLACE	L Rear Combination Lamp		997 631 485 03	278.55	INC	
87	AUTO	BDY	OVERHAUL	Rear Bumper Cover Assy					2.2 #
88	001522	BDY	REMOVE/REPLACE	Rear Bumper Cover		997 505 941 04	1,809.65	INC	#
89	AUTO	REF	REFINISH	Rear Bumper Cover					C 3.0
90	002339	BDY	REMOVE/REPLACE	Rear Bumper Foil		997 504 631 00	4.12	0.2	#
91	001534	BDY	REMOVE/REPLACE	Rear Upr Bumper Isolator Heat Shield		996 505 471 00	48.67	INC	
92	AUTO	REF	ADD'L OPR	Clear Coat					4.1
93	AUTO		ADD'L COST	Paint/Materials			651.00	*	
94	AUTO		ADD'L COST	Hazardous Waste Disposal			3.65	*	

\* - Judgment Item  
 # - Labor Note Applies  
 C - Included in Clear Coat Calc  
 r - CEG R&R Time Used For This Labor Operation

## Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	65.7	40.00	0.00	0.00	2,628.00 T	Taxable Parts	16,577.59
Refinish	21.7	40.00	0.00	0.00	868.00 T	Sales Tax @ 9.750%	1,616.32
Glass	0.6	55.00	0.00	0.00	33.00 T		
Mechanical	17.4	85.00	0.00	0.00	1,479.00 T	Total Replacement Parts Amount	18,193.91
					Taxable Labor 5,008.00		
Labor Summary	105.4				5,008.00		
III. Additional Costs					Amount	IV. Adjustments	Amount
Taxable Costs					651.00	Customer Responsibility	0.00
Sales Tax @ 9.750%					63.47		
Non-Taxable Costs					3.65		
Total Additional Costs					718.12		
Paint Material Method: Rates Init Rate = 30.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I. Total Labor:	5,008.00
						II. Total Replacement Parts:	18,193.91
						III. Total Additional Costs:	718.12
						Gross Total:	23,920.03
						IV. Total Adjustments:	0.00
						Net Total:	23,920.03

**This is a preliminary estimate.**  
**Additional changes to the estimate may be required for the actual repair.**