

## P1508

### 408 Torque comparison function monitor - signal implausible

#### Diagnosis conditions

- Engine speed greater than 1,120 rpm

#### Possible fault cause

- ◆ DME control module faulty

#### Affected terminals

#### Diagnosis/troubleshooting

Work instruction		Display OK	If not OK
1	Replace DME control module	⇒ Step 2	
2	Perform adaptation <ul style="list-style-type: none"> <li>◆ Switch on the ignition</li> <li>◆ Wait one minute</li> <li>◆ Do not press the accelerator</li> <li>◆ Switch off the ignition for at least 10 seconds</li> <li>◆ Read out the fault memory</li> </ul>	→ End	→ End