

Address 72: Door, Rear Right (J389) Labels: 4H0-959-795.clb
Part No SW: 4H0 959 795 A HW: 4H0 959 795 A
Component: TSG HR H04 0162
Revision: ----- Serial number: 0000118815419
Coding: 010F1F200200064006000104
Shop #: WSC 00083 790 00174
VCID: 3924427B09578D42085-806C

No fault code found.

Address 81: Gear Shift (J587) Labels: 3Y0-927-731.clb
Part No SW: 3Y0 927 731 A HW: 3Y0 927 731 A
Component: GSM-LL H05 0778
Revision: 0L0D5011 Serial number: SN110726 0106
ASAM Dataset: EV_GSM2x3Mono 001012
R0D: EV_GSM2x3Mono_BY83.rod
VCID: 3A265D770CD1865A01F-806E

1 Fault Found:
10022 - Unlock Button
P17EC 00 [137] - Electrical Malfunction
MIL ON - Confirmed - Tested Since Memory Clear

Freeze Frame:
Fault Status: 00000001
Fault Priority: 4
Fault Frequency: 1
Reset counter: 172
Mileage: 24651 km
Date: 2023.10.21
Time: 16:29:57

Voltage terminal 15: 12.2 V
Voltage terminal 30: 12.4 V
Driving position: P
Selector lever position: drive lane (X)
Unlock button signal: 4.9 V

Address 88: Multicont. Seat Driver (J873) Labels: * None
Part No SW: 4H0 907 182 G HW: 4H0 907 182 G
Component: IVB H08 0042
Serial number: 00001867152801 Dataset Number: V03935145AZ 0001
Coding: 704000
Shop #: WSC 00083 790 00240
ASAM Dataset: EV_IVBDriveSideFrnt 001003
R0D: EV_IVBDriveSideFrnt.rod
VCID: 2E0E6127C0995AFAAD7-807A

No fault code found.