

SERVICE BULLETIN		
To: All Dealers/MEAM Attention of: Service Manager Copy to: Aston Martin Technician(s) Dealer Principal Parts Manager	Reference: SB: 0239 Issued: May 2007	
Model: DB9 & V8 Vantage Safe VIN's: DB9 A00001-B07577 V8 C00001-C04625		
Subject: Ambient Temperature Display Inaccurate	Page 1 of 1	

Issue

This Service Bulletin is to advise the Dealer network that should a customer complain that their Ambient Temperature is incorrect, especially at low temperatures, that an improved Ambient Temperature sensor is now available via Parts Operations.

Workshop Procedure

1. Replace the Ambient Temperature Sensor using Part Number: 7G33-19E642-AA.

Part Number	Description	Qty	Time Allowance	Operation Number
7G33-19E642-AA	Ambient Temperature Sensor	1	0.50hrs	12.04.AC

Warranty

Warranty Claims are acceptable on a Complaint Only Basis, and should be administrated in the normal way with an associated Warranty Authorization Number.

If you have any queries in connection with any aspect of this Service Bulletin, please contact Aston Martin Technical Services on: + 44 (0) 1926 644720 or facsimile: +44 (0) 1926 644733. E-mail: amtech@astonmartin.com Alternatively, contact your After Sales Manager.

Thank you for your co-operation in this matter.