

# DRIVERSOURCE

FINE MOTORCARS

14750 Memorial Dr, Houston, TX 77079

281.497.1000

www.driversource.com

# Invoice

**PAID**  
09/26/2014

Date	Invoice #
9/1/2014	17497

Bill To	Vehicle	VIN	License
	2008 997 Carrera S	WP0AB29968S730457	
	Mileage	Engine	Rep
	19857		
		Terms	Due Upon Receipt

Quantity	Item Code	TR	Description	Price Each	Amount
2	SR022SG		BBS SR Wheel 18x8	325.00	650.00T
1	Shipping		Shipping	56.54	56.54
2	SR 20213		Schroth Profi II 6-pt Harness Set, Red, Hans	405.50	811.00T
1	Shipping		Shoulder Wrap		
1	997 044 802 51 ...		Shipping	14.50	14.50
1	Sublet Repair		Carrera S Decal	225.00	225.00T
1	Sublet Repair		Labor to apply decal	95.00	95.00
1			Apply matte black finish to hood, mirrors, and fuel door	565.00	565.00
1	P45 21 19 SILV...		Pedal Set 3 Piece	135.00	135.00T
1	Shipping		Shipping, overnight per customer approval	63.00	63.00
1	Labor-Customers		Install 4 piece pedal set	120.00	120.00
1	FE09 B		Rennline Fire Extinguisher Mount	174.00	174.00T
1	FE10 MX250R		H3R 2.5lb Fire Extinguisher	79.20	79.20T
1	Shipping		Shipping	35.00	35.00
1	Labor-Customers		Install new intake system.	120.00	120.00
1	INTKVF997NA		V-Flow Intake System	595.00	595.00T
1	Shipping		Shipping	22.00	22.00

I authorize repairs with parts and grant permission to operate vehicle for the purpose of testing and/or inspection. A mechanics lien is acknowledged to secure the amount of repairs thereto. We will not be held responsible for loss/damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond our control.

NOTICE PURSUANT TO 70.001, TEXAS PROPERTY CODE; I am the person or agent acting on behalf of the person obligated to pay for the repair of the motor vehicle subject to the repair contract. I understand that this vehicle is subject to repossession in accordance with 9.503, Texas Business & Commerce Code, if a written order for payment for repair on the vehicle is stopped, dishonored because of insufficient funds, no funds, or because the drawer of make or maker of the order has no account or the account on which it is drawn has been closed.

<b>Sales Tax (8.25%)</b>	\$1,339.63
--------------------------	------------

<b>Total</b>	\$21,040.98
--------------	-------------

<b>Balance Due</b>	\$0.00
--------------------	--------

(Signature) \_\_\_\_\_ Page 2

# DRIVERSOURCE

## FINE MOTORCARS

14750 Memorial Dr, Houston, TX 77079  
281.497.1000  
www.driversource.com

# Invoice

Date	Invoice #
9/1/2014	17497

**PAID**  
09/26/2014

Bill To	Vehicle	VIN	License
	2008 997 Carrera S	WP0AB29968S730457	
	Mileage	Engine	Rep
	19857		
		Terms	Due Upon Receipt

Quantity	Item Code	TR	Description	Price Each	Amount
1	Labor-Customers		Customer requests upgrades to vehicle for track day events. - Install adjustable anti-roll bars front and rear, Stainless steel brake lines, brake pads, flush brake system w/high-temp SRF brake fluid -Install 996 GT3 Bucket Seats, Half Roll Cage and steering wheel -Install racing suspension kit w/Alignment (shocks and springs, sway bars) -Mount/Balance 4 tires/wheels	2,000.00	2,000.00
1.5	Shop Supplies - ...		Shop Supplies	155.73	155.73T
1	SRF		SRF Brake Fluid	94.95333	142.43T
1	2131608		GT2 RS Alcantara Shift Knob	205.00	205.00T
1	Shipping		Shipping	10.08	10.08
1	BSN 48 136648		Performance Suspension System	3,803.00	3,803.00T
1	HB667G622		Hawk Track Pads	316.00	316.00T
1	G37035 4		Goodridge Stainless Braided, G-Stop 4 line kit	175.00	175.00T
1	Shipping		Shipping	12.50	12.50
1	997FSBK		Swaybar w/bushings, Front, 26.8mm, 5 pos adj, 997.1, 987 & Cayman	456.00	456.00T
1	997.2RSB		Swaybar w/bushings, Rear, 25.6mm, 3 way adj	611.32	611.32T
1	RSBADP997.2		Adaptor Kit, rear 997 GT3	146.25	146.25T
1	996FDLNK		Drop Link Pair, Front	264.00	264.00T
1	996RDLNK		Drop Link pair, Rear	182.00	182.00T
1	Shipping		Shipping	32.00	32.00
1	WC ROLL BAR...		GMG World Challenge Roll Bar 996/997	2,340.00	2,340.00T
2	070 98 UU11		Recaro Pole Position Black Velour White Logo	899.00	1,798.00T
1	Shipping		Shipping	145.00	145.00
1	Shipping		Shipping	25.05	25.05
2	46843r6		Hoosier R6 Tire, 295 30ZR18	423.50	847.00T
2	46821R7		Hoosier R7 245 35ZR18 Tire	423.50	847.00T
1	Shipping		Shipping	115.25	115.25
1	NM202		996/997 Shift Cable Assembly	630.00	630.00T
1	Shipping		Shipping	32.50	32.50
2	SR021SG		BBS SR Wheel 18x10	325.00	650.00T

I authorize repairs with parts and grant permission to operate vehicle for the purpose of testing and/or inspection. A mechanics lien is acknowledged to secure the amount of repairs thereto. We will not be held responsible for loss/damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond our control.

NOTICE PURSUANT TO 70.001, TEXAS PROPERTY CODE; I am the person or agent acting on behalf of the person obligated to pay for the repair of the motor vehicle subject to the repair contract. I understand that this vehicle is subject to repossession in accordance with 9.503, Texas Business & Commerce Code, if a written order for payment for repair on the vehicle is stopped, dishonored because of insufficient funds, no funds, or because the drawer of make or maker of the order has no account or the account on which it is drawn has been closed.

Sales Tax (8.25%)

Total

Balance Due

# DRIVERSOURCE

## FINE MOTORCARS

14750 Memorial Dr, Houston, TX 77079  
281.497.1000  
www.driversource.com

# Invoice

**PAYED**

Date	Invoice #
10/30/2014	17745

Bill To	Vehicle	VIN	License
	2008 997 Carrera	WP0AB29968S730457	
	Mileage	Engine	Rep
			LP
		Terms	
		Due Upon Receipt	

Quantity	Item Code	TR	Description	Price Each	Amount
1	48 115575		Bilstein PSS9 Coil Over Kit, Without PASM	3,503.50	3,503.50T
-1	BSN 48 136648		Performance Suspension System	3,503.50	-3,503.50T

I authorize repairs with parts and grant permission to operate vehicle for the purpose of testing and/or inspection. A mechanics lien is acknowledged to secure the amount of repairs thereto. We will not be held responsible for loss/damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond our control.  
NOTICE PURSUANT TO 70.001, TEXAS PROPERTY CODE; I am the person or agent acting on behalf of the person obligated to pay for the repair of the motor vehicle subject to the repair contract. I understand that this vehicle is subject to repossession in accordance with 9.503, Texas Business & Commerce Code, if a written order for payment for repair on the vehicle is stopped, dishonored because of insufficient funds, no funds, or because the drawer of make or maker of the order has no account or the account on which it is drawn has been closed.

Sales Tax (8.25%)	\$0.00
Total	\$0.00
Balance Due	\$0.00

(Signature) \_\_\_\_\_

# DRIVERSOURCE

FINE MOTORCARS

14750 Memorial Dr, Houston, TX 77079

281.497.1000

www.driversource.com

# Invoice

**PAID**  
**10/30/2014**

Date	Invoice #
10/1/2014	17632

Bill To	Vehicle	VIN	License
	2008 997 Carrera	WP0AB29968S730457	
	Mileage	Engine	Rep
			LP
		Terms	Due Upon Receipt

Quantity	Item Code	TR	Description	Price Each	Amount
1	Labor-Customers		<p><b>**WARRANTY WORK**</b></p> <p>Install new headliner.</p> <p>-Removed seats, sunroof panel, c and a-pillar covers, rear view mirror, upper console and roll bar. Installed new headliner. Reinstalled interior.</p> <p>-A-pillar scuff/tear repaired.</p> <p>Check sunroof and report. Customer states not sitting flush.</p> <p>-Found sunroof panel out of adjustment, corrected.</p> <p>Customer states getting rattle from underneath shifter on heavy accel. Ensure shift cables are on tight. Customer states popped off at track and had to fix.</p> <p>-Removed center console and re-tightened and readjusted cables for less noise. Reinstalled console. Replaced new ball joint liners for shift cables with another new piece to prevent re-occurrence.</p> <p>Inspect carpet around where roll cage was installed previously. Customer states pieces of it not reinstalled correctly.</p> <p>-Inspected and cleaned up carpet around roll cage where installed as best as possible. Cage installation does not allow for carpet to be fully flush and if trimmed, will not fit correctly when cage removed.</p>	0.00	0.00
1	Labor-Customers		<p>Labor per below:</p> <p>- Code out and deactivate PASM system</p> <p>- Suspension changed out per agreement with customer</p>	150.00	150.00
1	Shop Supplies - ...		<p>- Replace tip switch for hood release</p> <p>Shop Supplies</p>	5.00%	7.50T

I authorize repairs with parts and grant permission to operate vehicle for the purpose of testing and/or inspection. A mechanics lien is acknowledged to secure the amount of repairs thereto. We will not be held responsible for loss/damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond our control.

NOTICE PURSUANT TO 70.001, TEXAS PROPERTY CODE; I am the person or agent acting on behalf of the person obligated to pay for the repair of the motor vehicle subject to the repair contract. I understand that this vehicle is subject to repossession in accordance with 9.503, Texas Business & Commerce Code, if a written order for payment for repair on the vehicle is stopped, dishonored because of insufficient funds, no funds, or because the drawer of make or maker of the order has no account or the account on which it is drawn has been closed.

<b>Sales Tax (8.25%)</b>
<b>Total</b>
<b>Balance Due</b>

(Signature) \_\_\_\_\_ Page 1

# DRIVERSOURCE

FINE MOTORCARS

14750 Memorial Dr, Houston, TX 77079

281.497.1000

www.driversource.com

## Invoice

**PAID**  
10/30/2014

Date	Invoice #
10/1/2014	17632

Bill To	Vehicle	VIN	License
	2008 997 Carrera	WP0AB29968S730457	
	Mileage	Engine	Rep
			LP
		Terms	Due Upon Receipt

Quantity	Item Code	TR	Description	Price Each	Amount
1	Sublet Repair		Perform four wheel alignment	129.95	129.95
1	AP 911 801		Agency Power Sport Steering Wheel, Full Alcantara	1,395.00	1,395.00T
1	997 613 105 02 ...		Tip switch	93.46	93.46T

I authorize repairs with parts and grant permission to operate vehicle for the purpose of testing and/or inspection. A mechanics lien is acknowledged to secure the amount of repairs thereto. We will not be held responsible for loss/damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond our control.

NOTICE PURSUANT TO 70.001, TEXAS PROPERTY CODE; I am the person or agent acting on behalf of the person obligated to pay for the repair of the motor vehicle subject to the repair contract. I understand that this vehicle is subject to repossession in accordance with 9.503, Texas Business & Commerce Code, if a written order for payment for repair on the vehicle is stopped, dishonored because of insufficient funds, no funds, or because the drawer of make or maker of the order has no account or the account on which it is drawn has been closed.

Sales Tax (8.25%)	\$123.42
Total	\$1,899.33
Balance Due	\$0.00