

## Safety Issue Type: Recalls

**June 07 2017** NHTSA Campaign Number: 17V368000

### Camshaft Controllers may Loosen and Fail

An engine stall can increase the risk of a crash.

**NHTSA Campaign Number** 17V368000

**Manufacturer** Porsche Cars North America, Inc.

**Components** ENGINE

**Potential Number of Units Affected** 17986

#### Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2010-2012 Panamera S, Panamera 4S and Panamera Turbo vehicles, 2011-2012 Panamera and Panamera 4 vehicles, and 2011 Cayenne S and Cayenne Turbo vehicles. The affected vehicles have camshaft controllers that may come loose inside the engine, potentially resulting in an engine stall.

#### Remedy

Porsche will notify owners, and dealers will replace the fastening screws for the camshaft adjusters, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AH08.

#### Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

## Associated Products (15)

#### Vehicle

MAKE	MODEL	YEAR
PORSCHE	PANAMERA	2011-2012
PORSCHE	CAYENNE S	2011
PORSCHE	CAYENNE TURBO	2011
PORSCHE	PANAMERA 4S	2010-2012
PORSCHE	PANAMERA S	2010-2012
PORSCHE	PANAMERA 4	2011-2012
PORSCHE	PANAMERA TURBO	2010-2012

## Associated Documents (1)

Recall Acknowledgement

**RCAK-17V368-8382.pdf** 243.667KB

<https://static.nhtsa.gov/odi/rci/2017/RCAK-17V368-8382.pdf>