

Q'ty	Part Number/Description	Price
2 - 0	Cut off Valve	143.00
		286.00

DUMONT'S Inc.
 712 W. California St
 Okla City, OK 73102
 405-232-6497

220730003

Customer Name: Calhoun, Jarrod
 Address: 996 F
 3610 Carnoustie Dr.
 City: NORMAN State: OK Zip: 73072
 Year: 03 Make: FORSCHE Model: 911 Vin Number: 405-283-6477
 License: ? Mileage: 0

Received: 07/30/12 11:28 am
 Terms

Repair Instructions:
 Oper
 01 diverter valves
 Check Noise in Engine, Replace Cut off Valve
 Labor Charge: 209.00

Total Parts: 286.00

Recommendations:
 Engine Oil lines

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

**OUR COMPANY
 APPRECIATES YOUR BUSINESS!
 THANK YOU!**

Payments: 1 08/03/12 518.97 Visa

07:12 am
 SurchARGE Total: 0.00

Total Labor: 209.00
 Total Parts: 286.00
 Haz Waste: 0.00
 Sublet Repairs: 0.00
 Shop Supplies: 0.00
 Tax: 23.97

Total Amount: 518.97
 Payment: 518.97
 Bal Due: .00

(Signature)



SERVICE

Date	Invoice #
9/7/2012	5487

Bill To
Jarrod Calhoun 3610 Cannouistic Drive Norman, OK 73072

Ship To	

VIN#	Mileage	Terms	Vehicle
WP0AB29435686404	21937	Due on receipt	2003 996 turbo

Description	Qty	Rate	Amount
oil and filter service	1	67.50	67.50
996.107.225.53 MAH Oil Filter	1	23.20	23.20T
Total Quartz 9000 Energy 5W-40	9.5	9.75	92.63T
remove stock muffler. one broke stud, remove stud by drilling and tapping out . replace with bolt. labor to torch holes in new muffler	3	67.50	202.50
		30.00	30.00
used 996 turbo muffler	1	200.00	200.00T

Subtotal	\$615.83
Sales Tax (8.25%)	\$26.06
Total	\$641.89
Payments/Credits	\$0.00
Balance Due	\$641.89

Phone #
405-330-9116

SERVICE

SERVICE



Date	Invoice #
8/10/2012	5465

Bill To
Jarrold Calhoun 3610 Cannouistic Drive Norman, OK 73072

Ship To


@ @

VIN#	Mileage	Terms	Vehicle
WP0AB29435686404	21540		2003 TT

Description	Qty	Rate	Amount
Labor to replace steering reservoir	1.2	67.50	81.00
AS Steering Oil Tank	1	901.04	901.04T

Subtotal	\$982.04
Sales Tax (8.25%)	\$74.34
Total	\$1,056.38
Payments/Credits	\$0.00
Balance Due	\$1,056.38

Phone #
405-330-9116



www.planet11eleven.com
ELEVEN
 AUTO GROUP L.L.C.

601 Westland Drive
 Edmond, OK 73013

SERVICE

Date	Invoice #
2/7/2013	5582

Bill To
Jarrold Calhoun 3610 Cannouistic Drive Norman, OK 73072

Ship To

VIN#	Mileage	Terms	Vehicle
WP0AB29435686404	23697	Due on receipt	2003 996 Turbo

Description	Qty	Rate	Amount
labor to change front differential fluid. Nothing unusual found on drain plug.		67.50	67.50
labor to change transaxle fluid. Nothing unusual found on drain plug		67.50	67.50
mobil 1 75/90 syntec. gear oil	6	23.50	141.00T
limited slip differential additive	2	13.75	27.50T
labor to remove stock muffler and install customer provided aftermarket unit.	4	67.50	270.00
right side door latch mechanisms 996 list 350.60	1	310.00	310.00T
labor to remove right side door latch assembly and replace with new. adjust window regulator	3	67.50	202.50
attempt to diagnose irregular whistling noise that occurs around 3000 rpm remove serpentine belt from accessories. found small cut on belt. noise was not present when belt was removed. individually spun tensioner pulleys, alternator, power steering ac compressor-clutch. no irregularities found/	1	67.50	67.50
Serpentine Belt list 100.48	1	48.06	48.06T

Subtotal	\$1,201.56
Sales Tax (8.25%)	\$43.44
Total	\$1,245.00
Payments/Credits	\$0.00
Balance Due	\$1,245.00

Phone #
405-330-9116