

Vehicle Diagnostic Report

Car Information

Brand : ASTON MARTIN

Quick Scan

Marelli transmission control module	3	
Marelli transmission control module	3	
P0905	Shift position signal wrong value	Missed
P1734	Failure to disengage current gear due to mechanical cause	Missed
U1243	External ambient temperature from CAN Central Electronic Module (CEM) ECU signal invalid	Active