



8300 N. Lamar Blvd.

Austin, TX 78753

(512) 222-8867

LuxuryAutoWorks.com

Invoice # **0023042**

Service Advisor: Patrick C.

Date: 2/8/2022 Page 1 of 2

Center : 1

**12/12 WARR, OPT 36/36 WARR ON ALL PARTS AND LABOR**

**Customer :** Henson, Alan  
**Address :** 302 Sinclair  
**City :** BRIARCLIFF, TX 78669-  
**Cell :** ( 713 ) 304-2530  
**Home :** ( 512 ) -

**Vehicle :** 2005 Bent Continental gt  
**License :** RLF8026 **Mileage :** 13011  
**VIN :** SCBCR63W15C024726  
**Engine :** 6.0 W12  
**Trans :** AUTO

Quantity	Service Description	Part Description	Reason for Replacement	Labor	Parts	Subtotal
	Courtesy vehicle inspection, inspect vehicle for any safety related issues, inspect brake system, chassis, suspension components, belts, hoses, top off and inspect all fluids, test battery and charging system, road test vehicle			0.00		
	3 year, 36000 mile nationwide warranty on parts and labor, also includes complimentary jump start, towing for failure of replaced components, lock out service, and fueling. This warranty covers all parts that are not considered wearable service items. This warranty is operated by a third party. 866-588-0728			19.99		19.99
	Check engine light is on and fault code is present for lean mixture, bank 2 intercooler hose is swollen from oil, and bank 1 intercooler was damaged and repaired, replace both intercooler hoses and bank 1 intercooler			3975.00	5431.33	9406.33
1.00		INTERCOOLER			1279.05	
1.00		HOSE			254.96	
1.00		HOSE			295.62	
1.00		SPLASH GUARD			1533.62	
1.00		BOLT KIT SUBFRAME			1318.18	
1.00		SPLASH GUARD BOLT KIT			137.96	
1.00		AIR FILTER-LEFT			302.43	
1.00		AIR FILTER-RIGHT			309.51	
	Check engine light is on and fault codes are present for engine misfires, change engineoil and filter, replace spark plugs and ignition coils			1113.00	1288.62	2401.62
12.00		SPARK PLUG			348.72	
12.00		IGNITION COIL			759.96	
14.00		MOBIL 1 OIL			142.24	
1.00		OIL FILTER KIT			17.50	
1.00		MOA Oil Additive			20.20	
	Check engine light is on and fault code is present for exhaust gas temperature sensors, replace sensors			1351.50	1454.54	2806.04
1.00		EGT SENSOR			727.27	
1.00		EGT SENSOR			727.27	
	Transmission fluid is leaking from the transmission pan gasket, replace gasket, connector and filter			715.50	671.90	1387.40
1.00		Trans Conditioner			18.90	
1.00		AT PAN GASKET			141.67	
1.00		AT FILTER			133.33	
9.00		AUTO TRANS FLUID			378.00	
	Serpentine belt is cracking, replace belt			695.00	378.09	1073.09
1.00		BELT			378.09	
	Windshield assembly, replace			1033.50	7144.89	8178.39
1.00		WINDSCREEN			6156.58	
1.00		SENSOR			988.31	
	Headliner, remove from vehicle and recover in a like material			2385.00	1122.45	3507.45
1.00		HEADLINER RECOVER			1122.45	



8300 N. Lamar Blvd.

Austin, TX 78753

(512) 222-8867

LuxuryAutoWorks.com

Invoice # 0023042

Service Advisor: Patrick C.

Date: 2/8/2022 Page 2 of 2

Center : 1

12/12 WARR, OPT 36/36 WARR ON ALL PARTS AND LABOR

Customer : Henson, Alan
Address : 302 Sinclair
City : BRIARCLIFF, TX 78669-
Cell : ( 713 ) 304-2530
Home : ( 512 ) -

Vehicle : 2005 Bent Continental gt
License : RLF8026 Mileage : 13011
VIN : SCBCR63W15C024726
Engine : 6.0 W12
Trans : AUTO

Table with 6 columns: Quantity, Service Description, Part Description, Reason for Replacement, Labor, Parts, Subtotal

DROP OFF

NOTES

ACCEPTANCE OF POSSESSION

I have examined the invoice and changes and I accept them without dispute. I accept possession of the vehicle and acknowledge that I have examined it and I release you from any claims for theft, damage or loss to the vehicle.

NOTICE PURSUANT TO § 70.001, TEXAS PROPERTY CODE
I AM THE PERSON OR AGENT ON BEHALF OF THE PERSON RESPONSIBLE TO PAY FOR THE REPAIR OF THE MOTOR VEHICLE SUBJECT TO THIS REPAIR CONTRACT.

Labor : \$11,288.49
Parts : \$17,491.82
Sublet : \$0.00
Other Fees : \$0.00
Supply Charges : \$99.00
Subtotal : \$28,879.31
Sales Tax : \$1,451.24
Total : \$30,330.55
Paid : \$0.00
Due : \$30,330.55

X \_\_\_\_\_
Signature of Owner/Responsible Person

X \_\_\_\_\_
Signature of Owner/Responsible Person



Mercedes-Benz • BMW • Lexus • Audi • Volkswagen • Land Rover • Porsche and all European Brands