

VCDS

Windows Based VAG/VAS Emulator Running on Windows 11 x64
VCDS Version: Release 23.11.0(x64) Data version: 20240322 DS351.0
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000 000000

Self-Diagnosis Log
Monday, 29, April, 2024, 17:54:55:31389

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY
Mileage: 106870km-66405mi Repair Order: 4

Chassis Type: ZA-BY62 (3W0)
Scan: 01 02 03 05 06 07 08 09 11 31 15 16 17 19 28 2E 34 36 37 38
46 47 48 53 56 5D 65 66 68 6C 6D 71 76 77

VIN: SCBEC9ZA1FC041826 Mileage: 106870km-66405miles

01-Engine -- Status: OK 0000
02-Auto Trans -- Status: OK 0000
03-ABS Brakes -- Status: OK 0000
04-Steering Angle -- Status: OK 0000
05-Acc/Start Auth. -- Status: OK 0000
06-Seat Mem. Pass -- Status: OK 0000
07-Control Head -- Status: OK 0000
08-Auto HVAC -- Status: Malfunction 0010
09-Cent. Elect. -- Status: OK 0000
11-Engine II -- Status: OK 0000
31-Engine other -- Status: OK 0000
15-Airbags -- Status: OK 0000
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: OK 0000
19-CAN Gateway -- Status: OK 0000
28-HVAC, Rear -- Status: Malfunction 0010
2E-Media Player 3 -- Status: OK 0000
34-Level Control -- Status: OK 0000
36-Seat Mem. Drvr -- Status: OK 0000
37-Navigation -- Status: Malfunction 0010
38-Roof Electronics -- Status: OK 0000
42-Door Elect, Driver -- Status: OK 0000
46-Central Conv. -- Status: Malfunction 0010
47-Sound System -- Status: OK 0000
48-Seat, Rear, DS -- Status: Malfunction 0010
52-Door Elect, Pass. -- Status: OK 0000
53-Parking Brake -- Status: OK 0000
56-Radio -- Status: Malfunction 0010
5D-Operations -- Status: Malfunction 0010
62-Door, Rear Left -- Status: OK 0000
65-Tire Pressure -- Status: Malfunction 0010
66-Seat, Rear -- Status: OK 0000
68-Wiper Electr. -- Status: Malfunction 0010
6C-Back-up Cam. -- Status: OK 0000
6D-Trunk Elect. -- Status: OK 0000
71-Battery Charger -- Status: OK 0000
72-Door, Rear Right -- Status: OK 0000
76-Park Assist -- Status: OK 0000
77-Telephone -- Status: OK 0000

VCDS
Self-Diagnosis Log
Monday,29,April,2024,17:54:55:31389
Page 2

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 01: Engine (J623-CVAA) Labels: None
Part No SW: 07C 906 023 AA HW: 07C 907 309
Component: ME17.1.6 H16 0301
Revision: MHH16--- Serial number: VWX3Z0N7005860 CVN: 62B65BDE
Coding: 0D2A0032432E00020003
Shop #: WSC 00083 790 00194
ASAM Dataset: EV_ECM60TMP11107C906023AA 001002
ROD: EV_ECM60TMP07C906023AA.rod
VCID: 6099B771DAC40ADA4F3-8034
VINID: 8D34954C9A910564C0101202189ED5BB6D

No fault code found.
Readiness: 1110 1101

Address 02: Auto Trans (J217) Labels:* None
Part No SW: 4W0 927 158 D HW: 0CU 927 760 A
Component: OBL 60 MPIRdW H16 0001
Revision: --H16--- Serial number: VWX3Z0N7005860 CVN: 9B27EED2
Coding: 000001
Shop #: WSC 00083 790 00192
ASAM Dataset: EV_TCMAL450211 002010
ROD: EV_TCMAL450211_BY62.rod
VCID: 3FDB540D07FA1522169-806A

No fault code found.

Address 03: ABS Brakes Labels: None
Part No SW: 4W0 614 517 C HW: 4W0 614 517 C
Component: ESP 8.1 4WD H01 1200
Revision: 000000000 Serial number: 000000000000000
Coding: 0002543
Shop #: WSC 00083 790 00194
VCID: 363531292400D46AC5F-8062

No fault code found.

VCDS
Self-Diagnosis Log
Monday,29,April,2024,17:54:55:31389
Page 3

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 05: Acc/Start Auth. Labels: 3D0-909-13x-05.lbl
Part No SW: 3D0 909 137 G HW: 3D0 909 137 G
Component: C0 Kessy 6850
Revision: 00H24072 Serial number: VWX3Z0N7005860
Coding: 0405741
Shop #: WSC 00083 790 00216
VCID: 2B03105DEF429982AA1-807E

Subsystem 1 - Part No: XXXXXXXXXXXX
Component: ELV XXXX

No fault code found.

Address 06: Seat Mem. Pass (J521) Labels: None
Part No SW: 4W0 959 760 A HW: 4W0 959 760
Component: MEM-BFS H04 0700
Revision: AA000000 Serial number: 00000096656687
Coding: D0081F0085070090090001010101002100012727000000
Shop #: WSC 00083 790 00242
VCID: 40D957F17AC46ADA6F3-8014

No fault code found.

Address 07: Control Head Labels: 3D0-907-048.clb
Part No SW: 3D0 907 048 HW: 3D0 907 048
Component: J127 KBT vorn 0100
Revision: ABH23001 Serial number: VWZ6Z7P0131021
Shop #: WSC 00000 000 00000
VCID: 6393B87DC71211C2521-8036

No fault code found.

Address 08: Auto HVAC Labels: None
Part No: 3W5 907 040 K
Component: Climatronic BY621 3030
Coding: 0000101
Shop #: WSC 00083 790 00216
VCID: 3E2529090C301C2A1DF-806A

1 Fault Found:
00477 - Control Module; Display & Input; Comfort CAN; Front (J523)
004 - No Signal/Communication - Intermittent

VCDS
Self-Diagnosis Log
Monday,29,April,2024,17:54:55:31389
Page 4

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 09: Cent. Elect. Labels: 3D0-937-049-V2.clb
Part No SW: 3D0 937 049 Q HW: 3D0 937 049 Q
Component: J519 7700
Revision: -4007--- Serial number: -----
Coding: 40820000AB2A11C02508030000000000
Shop #: WSC 00083 790 00216
VCID: 38293F112E14221AD73-806C

No fault code found.

Address 11: Engine II (J624) Labels: None
Part No SW: 07C 906 023 AA HW: 07C 907 309
Component: ME17.1.6 H16 0301
Revision: MHH16--- Serial number: VWX3Z0N7005860 CVN: 62B65BDE
Coding: 0D2A0032432E00020003
Shop #: WSC 00083 790 00194
ASAM Dataset: EV_ECM60TMP21107C906023AA 001002
ROD: EV_ECM60TMP07C906023BR.rod
VCID: 6099B771DAC40ADA4F3-8034

No fault code found.

Page 5

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

[illegible]

Seat occupied recognition:
Subsystem 1 - Part No SW: 4W0 959 339 A HW: 4W0 959 339 A
Component: BF-Gewichtss. H03 0201
Serial number: 5850000R144150AH0Y

Crash sensor for side airbag: driver side:
Serial number: 3572DRB40000F64CE8DF

Front Passenger's Side Airbag Crash Sensor:
Serial number: 3582DRB40000F63069A-

Rear Side Airbag Crash Sensor (on driver's side):
Serial number: 35128RB40000719B3B5M

Passenger side rear thorax airbag crash sensor:
Serial number: 35228RB40000719BCB6X

Crash sensor for front airbag: driver side:
Serial number: 35547RB40000721CE4DX

Crash sensor for front airbag: front passenger side:
Serial number: 35647RB40000721E152D

No fault code found.

Address 16: Steering wheel Labels: 7L6-953-549.Ibl
Part No: 7L6 953 549 K
Component: J527 3601
Coding: 0000032
Shop #: WSC 00083 790 00244
VCID: 47CB4CED53EA5DE2AE9-8012

No fault code found.

VCDS
Self-Diagnosis Log
Monday,29,April,2024,17:54:55:31389
Page 6

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 17: Instruments Labels: 3Wx-920-xxx-17.clb
Part No SW: 3W0 920 851 R HW: 3W0 920 851 R
Component: J285 KOMBI-INST. 5555
Revision: KPH10V04
Coding: 0034214
Shop #: WSC 00046 000 00000
VCID: 45D746E569A64FF25C5-8010

No fault code found.

Address 19: CAN Gateway Labels: None
Part No SW: 3W0 909 901 HW: 3W0 920 851 R
Component: J533 GW-K-CAN TP20 5555
Revision: KPH10V04
Coding: 5FFAFFFFEB551702
Shop #: WSC 00046 000 00000
VCID: 76B5F12964C0946A05F-8022

No fault code found.

Address 28: HVAC, Rear (J524) Labels: None
Part No SW: 4W0 035 008 HW: 4W0 035 008
Component: CLIMATE ECU H06 0062
Revision: P0H06004 Serial number: 51400088633001
Coding: 00000000010102
Shop #: WSC 00000 000 00000
VCID: 6B83D05D23C25982EA1-803E

Subsystem 1 - Part No SW: 4W0 907 042 A HW: 4W0 907 042
Component: RBM-BY621 H09 0055
Serial number: WA109279000006906992

1 Fault Found:

04062 - Remote Display and Operating Unit 1 -- Software Version
000 - -

Freeze Frame:

Fault Status: 01100000
Fault Priority: 3
Fault Frequency: 1
Reset counter: 147
Mileage: 106879 km
Time Indication: 0
Date: 2024.04.29
Time: 07:45:25

VCDS
Self-Diagnosis Log
Monday,29,April,2024,17:54:55:31389
Page 7

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 2E: Media Player 3 (J650) Labels: 5N0-035-342.lbl
Part No SW: 5N0 035 342 G HW: 5N0 035 342 G
Component: SG EXT.PLAYER H19 0770
Revision: A1001003 Serial number: 7666254327
Coding: 030100
Shop #: WSC 00083 790 00192
VCID: 2B03105DE3029982AA1-807E

No fault code found.

Address 34: Level Control Labels: None
Part No: 4W0 907 553
Component: LUFTFDR.-CDC- 3C3V0 7705
Coding: 0005541
Shop #: WSC 00083 790 00204
VCID: 78A9FF116E94E21A173-802C

No fault code found.

Address 36: Seat Mem. Drvr (J136) Labels: None
Part No SW: 4W0 959 760 A HW: 4W0 959 760
Component: MEM-FS H04 0700
Revision: AA000000 Serial number: 00000103730948
Coding: D0081F0085870090090001010101012100012727000000
Shop #: WSC 00083 790 00236
VCID: 40D957F17AC46ADA6F3-8014

No fault code found.

VCDS
Self-Diagnosis Log
Monday,29,April,2024,17:54:55:31389
Page 8

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 37: Navigation (J0506) Labels: 3D0-035-680.clb
Part No SW: 3W0 035 017 Q HW: 3W0 035 017 Q
Component: RNS-MID H23 0584
Revision: AB001001 Serial number: VWZ6Z7P0131021
Coding: 06010002000000044000
Shop #: WSC 00083 790 00216
VCID: 3B23201D136209023A1-806E

Subsystem 1 - Part No: 3W0 919 859 BN
Component: NAR V4 7963

1 Fault Found:

03138 - Input AUX IN
011 - Open Circuit
Freeze Frame:
Fault Status: 01101011
Fault Priority: 5
Fault Frequency: 1
Reset counter: 147
Mileage: 106879 km
Time Indication: 0
Date: 2024.04.29
Time: 17:34:54

Address 38: Roof Electronics Labels: None
Part No: 3W0 907 135 H
Component: Dachmodul 0910
Coding: 0020493
Shop #: WSC 00083 790 00194
VCID: 3B23201D1F2209023A1-806E

No fault code found.

Address 46: Central Conv.
Cannot be reached

Address 47: Sound System Labels: None
Part No SW: 4W0 035 465 HW: 4W0 035 465
Component: DSP 10 Kanal 0010
Revision: 00H08001 Serial number: 75824012864504
Shop #: WSC 00000 000 00000
VCID: 72BDCD3908A8884A297-8026

No fault code found.

VCDS
Self-Diagnosis Log
Monday,29,April,2024,17:54:55:31389
Page 9

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 48: Seat, Rear, DS
Cannot be reached

Address 53: Parking Brake (J540) Labels: None
Part No SW: 4W0 907 801 HW: 4W0 907 801
Component: EPB-4 H01 0002
Revision: ----- Serial number: 00000000001023 Dataset Number: V03935199CZ 0001
ASAM Dataset: EV_BY62XParkBrake 001008
ROD: EV_BY62XParkBrake.rod
VCID: 74B1CB217E3C867A3BB-8020

No fault code found.

Address 56: Radio (J0506) Labels: 3D0-035-680.clb
Part No SW: 3W0 035 017 Q HW: 3W0 035 017 Q
Component: RNS-MID H23 0584
Revision: AB001001 Serial number: VWZ6Z7P0131021
Coding: 060100020000000044000
Shop #: WSC 00083 790 00216
VCID: 3B23201D136209023A1-806E

Subsystem 1 - Part No: 3W0 919 859 BN
Component: NAR V4 7963

1 Fault Found:

03138 - Input AUX IN
011 - Open Circuit
Freeze Frame:
Fault Status: 01101011
Fault Priority: 5
Fault Frequency: 1
Reset counter: 147
Mileage: 106879 km
Time Indication: 0
Date: 2024.04.29
Time: 17:34:54

Address 5D: Operations
Cannot be reached

VCDS
Self-Diagnosis Log
Monday,29,April,2024,17:54:55:31389
Page 10

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 65: Tire Pressure Labels: 3D0-907-273-V5.clb
Part No SW: 3W7 907 273 D HW: 3W7 907 273 D
Component: J0502 RDK 0007
Revision: 004007 Serial number: 00000600001312
Coding: 0000E03175CA4286EB75B9FD52EB0097FC004B6E4B6E4B6E4B64
Shop #: WSC 00083 790 00213
VCID: 41DF52F57DCE63D260D-8014

1 Fault Found:

00477 - Control Module; Display & Input; Comfort CAN; Front (J523)

004 - No Signal/Communication - Intermittent - MIL ON

Freeze Frame:

Fault Status: 10100100
Fault Priority: 3
Fault Frequency: 1
Reset counter: 187
Mileage: 106879 km
Time Indication: 0
Date: 2024.04.29
Time: 17:28:05

Freeze Frame:

(no units): 36.0

Address 66: Seat, Rear (J877) Labels: None
Part No SW: 4W0 959 760 A HW: 4W0 959 760
Component: MEM-BFS-Fond H04 0700
Revision: AA000000 Serial number: 00000103736099
Coding: C0081E8085810000090021000001000000002727000000
Shop #: WSC 00083 790 00154
VCID: 40D957F17AC46ADA6F3-8014

No fault code found.

Address 68: Wiper Electr. Labels: 3Wx-955-023.clb
Part No: 3W5 955 023 M
Component: Wischermodul 0401
Shop #: WSC 00000 725 65552
VCID: 44D15BE162DC76FA4BB-8010

1 Fault Found:

00459 - Control Module for Display and Input; Front (J523)

004 - No Signal/Communication

VCDS
Self-Diagnosis Log
Monday, 29, April, 2024, 17:54:55:31389
Page 11

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 6C: Back-up Cam. Labels: None
Part No SW: 4W0 907 441 HW: 4W0 907 441
Component: J772_Rearview 0030
Revision: 00H13000 Serial number: 525 PA8J440423
Coding: 2020003
Shop #: WSC 00083 790 00169
VCID: 74B1CB2172BC867A3BB-8020

No fault code found.

Address 6D: Trunk Elect. (----) Labels: 7N0-959-107.clb
Part No SW: 4W0 959 107 A HW: 4W0 959 107 A
Component: HDSG-Modul H04 0806
Revision: 000000000 Serial number: 043400039 Dataset Number: V03935220VP 0002
Coding: 170206C120
Shop #: WSC 09592 002 1048576
ASAM Dataset: EV_HDSGBY621 001002
ROD: EV_HDSGBY621.rod
VCID: 3B23201D13E209023A1-806E

No fault code found.

Address 71: Battery Charger (J367) Labels: *None
Part No SW: 3W3 915 181 B HW: 3W3 915 181 B
Component: EMM Batt Man H05 0570
Serial number: 0000000001
Coding: 5E0100
Shop #: WSC 00083 790 00213
ASAM Dataset: EV_BatteChargVaria1 002019
ROD: EV_BatteChargVaria1_002.rod
VCID: 38293F1122D4221AD73-806C

Battery Monitoring Control Module:

No fault code found.

Address 76: Park Assist Labels: 3W0-919-283-V3.clb
Part No SW: 3W0 919 283 G HW: 3W0 919 283 E
Component: J446 ST Parkhilfe 0111
Revision: 11H02001 Serial number: 58131412900244
Coding: 0300066
Shop #: WSC 00083 790 00216
VCID: 41DF52F57DCE63D260D-8014

No fault code found.

VCDS
Self-Diagnosis Log
Monday,29,April,2024,17:54:55:31389
Page 12

VIN: SCBEC9ZA1FC041826 License Plate: G3NTLY

Address 77: Telephone (J412) Labels:| 3C8-035-730-A.clb
Part No SW: 3D0 035 730 D HW: 3D0 035 730 D
Component: Telefon 024 0982
Revision: ----- Serial number: 35502105143186
Coding: 0201060101000100000000001
Shop #: WSC 00083 790 00216
ASAM Dataset: EV_UHVPremi 002709
ROD: EV_UHVPremi.rod
VCID: 1D67CE85AD366732245-8048

No fault code found.

End----- (Elapsed Time: 02:11, VBatt start/end: 12.2V/12.2V)-----