



PORSCHE

The Porsche Multi-Point Inspection Report

The Porsche Multi-Point Inspection Report is a series of thorough vehicle "health checks" performed by factory-trained Porsche technicians. It is designed to keep your Porsche operating in top condition and to minimize your chances of being inconvenienced on the road. If additional service is recommended on any listed item, your Porsche Service Advisor will be happy to speak with you about your options.

6/15
5/18
Roy Olivier

Customer Name

RO/Tag

719160

Mileage

10,163

Year/Model

VIN

13 911

WPOCB2A96DS155994/13/18

Engine Size

3.8 liter

Date

10/13/18

Checked and Okay at this Time

May Require Future Attention

Requires Immediate Attention

Check Fluid Levels and Fill

OK	FILL	OK	FILL
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engine Oil		Brake Reservoir	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Windshield Washer		Headlamp Washer	
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Power Steering		Coolant Recovery Reservoir	
<input type="checkbox"/>	<input type="checkbox"/>		
Transmission (if equipped w/ dipstick)			

Check Following Systems / Components

- Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps
- Visually inspect headlamp alignment
- Windshield washer spray, wiper operation and wiper blades
- Windshield cracks and/or chips
- Heating, ventilation and air conditioning check
- Engine air cleaner filter
- Oil and/or fluid leaks
- Constant velocity (CV) drive axle boots (if equipped)
- Exhaust system (leaks, damage, loose parts)
- Steering and steering linkages
- Shocks/struts, air suspension and other suspension components for leaks and/or damage
- Brake system (including lines, hoses and parking brake)
- Engine cooling system, hoses and clamps
- Radiator, heater and air conditioning hoses for leaks / damage
- Accessory drive belt(s)
- Clutch operation (if equipped)
- State inspection due (if applicable) _____/_____/_____
Month Day Year
- Your last completed maintenance _____; _____/_____
Mileage Month Year
- Your next factory scheduled maintenance is due at _____; _____/_____
Mileage Month Year


Comments:

Check Battery Condition

- Good
 - Recharge
 - Bad
- Comments:

Check Brakes

Measure Front / Rear Brake Linings



- Over 5mm or 7/32" (Green bar)
- 3 to 5mm or 4/32" to 7/32" (Yellow bar)
- Less than 3mm or 4/32" (Red bar)

Brake Measurements Not Taken This Service Visit

Comments:

Check Tires

LF	TREAD DEPTH	RF
<input checked="" type="checkbox"/> 7/32" or Greater		<input checked="" type="checkbox"/> 7/32" or Greater
<input type="checkbox"/> 4/32" to 6/32"		<input type="checkbox"/> 4/32" to 6/32"
<input type="checkbox"/> 3/32" or Less		<input type="checkbox"/> 3/32" or Less
<input type="checkbox"/> 7/32" or Greater		<input type="checkbox"/> 7/32" or Greater
<input checked="" type="checkbox"/> 4/32" to 6/32"		<input checked="" type="checkbox"/> 4/32" to 6/32"
<input type="checkbox"/> 3/32" or Less		<input type="checkbox"/> 3/32" or Less
LR		RR

- LF Wear Pattern / Damage
 - LR Tire Wear Indicators
 - RF
 - RR
- Alignment Check Recommended Wheel Balance Recommended

Comments:

Nail in RR tire. Recommend replace

Tire Pressure Set to

Factory Recommendations PSI 32 Front 35 Rear

This Courtesy Inspection Completed By Your Porsche Service Team

Service Advisor:

Bianca Pinkerton

Technician:

T-22

Customer Signature: