

Full Diagnostic Report

Customer Name: N/A

Technician Name: Arjun

Diagnosis started: 10/06/2024 11:19:01

Diagnosis ended: 10/06/2024 11:31:34

Shop Name: Auto Grande	Telephone: N/A
SN: 988889103426	Email: N/A
Service Fee: USD	Repair Order No: N/A
Address: Hvundvegen 214	City: Skien
State/County: Skien	Country or region: Norway
Zip Code: 3746	Notes: N/A

Make: Bentley	Model: GT Speed
Year: 2009	Displacement: N/A
VIN: SCBCF63W19C060530	Odometer: 40480 km
Registration No. N/A	Vehicle Software Version: V10.24

Pre Scan

10/06/2024 11:31:34

System(7)	Status(2)
17 Instrument Cluster	Fault 1
19 Data Bus OBD Interface	Fault 1
05 Access/Start Authorization	No Fault
37 Navigation	No Fault
47 Sound System	No Fault
57 TV Tuner	No Fault
77 Telephone	No Fault

DTC

System	Code	Description	Status
17 Instrument Cluster	01325	Tire Pressure Monitoring Control Module	No Signal/Communication
19 Data Bus OBD Interface	01325	Tire Pressure Monitoring Control Module	No Signal/Communication

Customer Name: _____

Technician Name: _____

Date: _____